

Report ID: RDS-20260608172055

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	0
Medium	0
Minor	1
Confidence	73.9%

Road Health Score: 95%

Road Status: ■ Excellent

Image Name: 31_jpg.rf.c7096df6b5a1af9ae36ce92c1bf24216.jpg

Date: 08-06-2026 17:20:55

Total Potholes: 1

Severe Potholes: 0

Medium Potholes: 0

Minor Potholes: 1

Average Confidence: 73.9%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask