

Report ID: RDS-20260608171850

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	1
Medium	0
Minor	0
Confidence	87.08%

Road Health Score: 80%
Road Status: ■ Excellent

Image Name: 325.jpg
Date: 08-06-2026 17:18:50
Total Potholes: 1
Severe Potholes: 1
Medium Potholes: 0
Minor Potholes: 0
Average Confidence: 87.08%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask