


Report ID: RDS-20260608234608

SMART ROAD DAMAGE DETECTION REPORT

Detection Result



Parameter	Value
Total Potholes	3
Severe	0
Medium	3
Minor	0
Confidence	79.22%

Road Health Score: 70%

Road Status: ■ Fair

Image Name: 36_jpg.rf.a4ac2defeea35c6c543ad55898d5e8c0.jpg

Date: 08-06-2026 23:46:08

Total Potholes: 3

Severe Potholes: 0

Medium Potholes: 3

Minor Potholes: 0

Average Confidence: 79.22%

Generated by Smart Road Damage Detection System

YOLOv8 | *OpenCV* | *Flask*