

Report ID: RDS-20260608171113

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	2
Severe	1
Medium	1
Minor	0
Confidence	85.32%

Road Health Score: 70%

Road Status: ■ Fair

Image Name: 42_jpg.rf.280ed750df2173993c1bdd1853a0e5b0.jpg

Date: 08-06-2026 17:11:13

Total Potholes: 2

Severe Potholes: 1

Medium Potholes: 1

Minor Potholes: 0

Average Confidence: 85.32%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask