

Smart Road Damage Detection Report

Image Name: 51_jpg.rf.8117c6d9b01c1977e7e9c1bad5c91bd9.jpg

Date: 2026-06-06 16:42:16.107822

Total Potholes: 1

Severe Potholes: 0

Medium Potholes: 1

Minor Potholes: 0

Average Confidence: 83.59%