

Report ID: RDS-20260608141033

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	0
Medium	1
Minor	0
Confidence	83.94%

Road Health Score: 90%

Road Status: ■ Excellent

Image Name: 66_jpg.rf.a0d4fece3d1a4bcba179d0b2ea29ac45.jpg

Date: 08-06-2026 14:10:33

Total Potholes: 1

Severe Potholes: 0

Medium Potholes: 1

Minor Potholes: 0

Average Confidence: 83.94%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask