

Report ID: RDS-20260608171551

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	0
Medium	0
Minor	1
Confidence	70.4%

Road Health Score: 95%

Road Status: ■ Excellent

Image Name: potholes137_png.rf.fac702cc2f793bec7ace4a4c0db3d67c.jpg

Date: 08-06-2026 17:15:51

Total Potholes: 1

Severe Potholes: 0

Medium Potholes: 0

Minor Potholes: 1

Average Confidence: 70.4%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask