

Report ID: RDS-20260608171209

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	0
Medium	1
Minor	0
Confidence	80.34%

Road Health Score: 90%

Road Status: ■ Excellent

Image Name: potholes191_png.rf.bec1dcca9bf9eb04e617de751a96b574.jpg

Date: 08-06-2026 17:12:09

Total Potholes: 1

Severe Potholes: 0

Medium Potholes: 1

Minor Potholes: 0

Average Confidence: 80.34%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask