

Report ID: RDS-20260608171335

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	1
Medium	0
Minor	0
Confidence	85.35%

Road Health Score: 80%

Road Status: ■ Excellent

Image Name: potholes416_png.rf.219843818dda50af403db3bbd30305f5.jpg

Date: 08-06-2026 17:13:35

Total Potholes: 1

Severe Potholes: 1

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 85.35%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask