


Report ID: RDS-20260608171631

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	3
Severe	1
Medium	2
Minor	0
Confidence	82.54%

Road Health Score: 60%

Road Status: ■ Fair

Image Name: potholes658_png.rf.4b4154fd7766a1871d246b8c2aa4b6df.jpg

Date: 08-06-2026 17:16:31

Total Potholes: 3

Severe Potholes: 1

Medium Potholes: 2

Minor Potholes: 0

Average Confidence: 82.54%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask