

Report ID: RDS-20260608171535

# SMART ROAD DAMAGE DETECTION REPORT

## AI Powered Road Inspection System

### Detection Result



| Parameter      | Value  |
|----------------|--------|
| Total Potholes | 1      |
| Severe         | 1      |
| Medium         | 0      |
| Minor          | 0      |
| Confidence     | 86.24% |

Road Health Score: 80%

**Road Status:** ■ Excellent

Image Name: potholes78\_png.rf.f45aca67b1bba1d975d9a082cd7c9989.jpg

Date: 08-06-2026 17:15:35

Total Potholes: 1

Severe Potholes: 1

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 86.24%

*Generated by Smart Road Damage Detection System*

*YOLOv8 | OpenCV | Flask*