RoadVision AI

Road Damage Inspection Report · 4 Detection(s) · Generated 17 September 2026 at 16:15

Summary

Total Detections	High Priority	Medium Priority	Damage Types
4	1	3	3

Detected Damages

ID	Damage Class	Confidence	Severity	Location	Timestamp	Device
6	Longitudinal Crack	37.5%	Medium	70.0000, 85.0000	17 Sep 2026, 16:14	upload
5	Longitudinal Crack	74.6%	Medium	70.0000, 85.0000	17 Sep 2026, 16:14	upload
4	Transverse Crack	73.7%	Medium	N/A	05 Sep 2026, 23:26	webcam
1	Alligator Crack	85.9%	High	30.5594, 76.7207	05 Sep 2026, 20:06	phone

Analytics





Recommendations

Based on the analysis, 1 location(s) require immediate attention (High priority) and 3 location(s) should be scheduled for repair soon (Medium priority). High priority damages include potholes and alligator cracks which pose significant safety risks to vehicles and pedestrians.