

COASTLINE MATERIALS TESTING LAB

220 Harbor Industrial Way · Tacoma, WA 98421 · (253) 555-0193 · www.coastline-mtl.example
AIHA-LAP Accredited (Bulk Asbestos) — Cert. No. WA-A0417 | NVLAP Lab Code 200456-0

BULK ASBESTOS ANALYSIS REPORT — PRE-DEMOLITION SURVEY

REPORT NO. CMT-26-3390	DATE REPORTED June 03, 2026
CLIENT Sound & Vine Demolition Inc.	PROJECT / SITE Former Cascade Warehouse, 1140 Dock St, Tacoma WA
SAMPLE IDS ACM-01 through ACM-06	SAMPLE MATRIX Floor Tile, Mastic, Pipe Insulation, Joint Compound
DATE COLLECTED May 28, 2026	DATE RECEIVED May 29, 2026, 11:20 PDT
COLLECTED BY S. Nguyen (Certified Asbestos Inspector, #WA-9021)	CHAIN OF CUSTODY NO. COC-20984

1. Case Narrative

Six (6) bulk building material samples were submitted ahead of planned demolition to identify asbestos-containing material (ACM) requiring abatement prior to structural work. Samples were analyzed by PLM with dispersion staining; positive stop was not applied per client instruction (full point-count requested).

2. Sample Results

Sample ID	Material Description	Asbestos Detected	Fiber Type / % Content	Flag
ACM-01	9" x 9" floor tile, beige	Detected	Chrysotile, 3%	Detected
ACM-02	Black mastic beneath ACM-01	Detected	Chrysotile, 5%	Detected
ACM-03	Pipe insulation, corridor B	Detected	Chrysotile, 35%	Detected
ACM-04	Joint compound, drywall seams	Non-Detect	None observed	Non-Detect
ACM-05	Ceiling tile, 2x4 lay-in	Non-Detect	None observed	Non-Detect
ACM-06	Roofing felt, loading dock	Detected	Chrysotile, 8%	Detected

3. Regulatory Classification

Materials containing greater than 1% asbestos by PLM are regulated as ACM under 40 CFR Part 61 Subpart M (NESHAP) and OSHA 29 CFR 1926.1101. Samples ACM-01, ACM-02, ACM-03, and ACM-06 are classified as ACM and require licensed abatement and proper notification prior to disturbance during demolition.

4. Recommendations

Client should engage a licensed asbestos abatement contractor for identified positive materials, file required NESHAP demolition notification with the state agency at least 10 working days prior to demolition, and arrange manifested disposal of ACM waste at a permitted landfill accepting asbestos-containing waste.

Analysis performed by Polarized Light Microscopy (PLM) per EPA Method 600/R-93/116. This report relates only to the samples submitted and shall not be used to certify a full building survey.

T. Reyes, PLM Analyst / Lab Supervisor

Date: June 03, 2026

This report shall not be reproduced except in full, without the written approval of COASTLINE MATERIALS TESTING LAB. Results are illustrative and fictional — for template/reference use only.