

TRIVALLEY ENVIRONMENTAL TESTING SERVICES

3060 Industrial Loop, Bldg C · Fresno, CA 93706 · (559) 555-0637 · www.trivalley-ets.example
ELAP Accredited (CA Dept. of Public Health) — Cert. No. CA-4471 | ISO/IEC 17025:2017

WASTE PROFILE ANALYTICAL REPORT — PARTS WASHER SLUDGE

REPORT NO. TVE-26-2205	DATE REPORTED April 09, 2026
CLIENT Valley Fleet Services LLC	PROJECT / SITE Fresno Maintenance Yard — Bay 3 Parts Washer
SAMPLE ID VFS-PW3-SLUDGE01	SAMPLE MATRIX Parts Washer Sludge (Semi-Solid)
DATE COLLECTED April 01, 2026, 08:30 PDT	DATE RECEIVED April 02, 2026, 10:00 PDT
COLLECTED BY A. Kim (Shop Supervisor)	CHAIN OF CUSTODY NO. COC-38221

1. Case Narrative

A composite sludge sample was collected from the bottom of a parts-washer solvent reservoir during routine maintenance to support hazardous waste determination and proper disposal/recycling routing. Used oil filter crush residue from the same bay was included per client request as sample -02.

2. Physical & Bulk Characteristics

Parameter	Result	Method	Flag
pH	8.9 SU	SW-846 9045D	Pass
Flash Point	165 °F	ASTM D93	Review
Total Petroleum Hydrocarbons (TPH)	62,300 mg/kg	SW-846 8015D	—
% Total Solids	41.2 %	SM 2540 G	—

3. TCLP Metals (Method 1311 / 6010D)

Analyte	Result (mg/L)	RCRA Limit (mg/L)	Flag
Lead	1.84	5.0	Pass
Chromium (Total)	0.34	5.0	Pass
Cadmium	< 0.005	1.0	Pass
Zinc (Total, informational)	410	—	—

4. Halogenated Organics Screen

Parameter	Result	Method	Threshold	Flag
Total Organic Halogens (TOX)	890 mg/kg	SW-846 9020B	1,000 mg/kg (used oil rule)	Pass

TOX below the 1,000 mg/kg rebuttable presumption threshold under 40 CFR 279.10; used oil is presumed not mixed with halogenated solvent.

5. Waste Classification Summary

Flash point below 200°F warrants handling precautions but is above the 140°F RCRA ignitability threshold (D001 not applicable). TCLP metals are within RCRA limits. Material is non-hazardous by RCRA characteristic testing and may be managed as used oil / non-hazardous industrial waste, subject to facility-specific acceptance criteria.

I certify this data has been reviewed for completeness and accuracy and meets the laboratory's ELAP-accredited quality assurance requirements.

C. Ibarra, Laboratory Manager

Date: April 09, 2026

This report shall not be reproduced except in full, without the written approval of TRIVALLEY ENVIRONMENTAL TESTING SERVICES. Results are illustrative and fictional — for template/reference use only.