

FIELD INSPECTION REPORT - UNIT TR-900

Inspection ID: FIR-2026-0915 | Location: Sector 4 Energy Facility | Date: 2026-09-15

1. Executive Summary & Operating Parameters

Routine quarterly inspection performed on Turbine Generator Set TR-900 while running. Operational telemetry was collected under heavy base-load conditions.

2. Recorded Engineering Measurements

Parameter	Measured Value	Technician Note
Rotor Operating RPM	3,600 RPM	Synchronous 60 Hz
Hydraulic Fluid Pressure	245.0 Bar	Pressure high due to line regulator setting
Lubricant In Use	Mineral SAE 30	Refilled by maintenance contractor
Bearing Housing Condition	Pristine (No Defect)	Visual check by inspector

3. Inspector Conclusion & Follow-up Actions

The technician notes elevated pressure readings and recommended a comprehensive engineering comparison against technical baseline specifications before certifying next quarterly cycle.