

Checklist for BPCL Admin Building

- ☒ Oil Leakage ☒ Encroachment
- ☐ Fire Incident ☐ Missing of Boundary pillars
- ☐ Wastages/Plastic bins ☐ Grass Cutting
- ☐ Removal of trees/branches ☐ Filling of earth hole
- ☐ Replacement/Repairing of Warning boards
- ☐ Checking of Cattles ☐ TLP Box"

Checklist for BPCL Entry Gate

- ☐ Oil Leakage ☐ Encroachment
- ☐ Dumping of Rail Sleepers, M/Sand Metal etc.
- ☒ Removal of trees/branches ☐ Grass Cutting
- ☒ Pipeline protection net, Door & lock"

Checklist for BPCL Admin Annex Building

- ☒ Oil Leakage ☒ Encroachment
- ☐ Removal of 03 X boundary pillars named 'SR' placed by the Railway
- ☐ Visibility of boundary pillars ☐ Grass Cutting
- ☐ Wastages/Plastic bins ☐ Missing of Boundary pillars
- ☐ Cultivation of Banana trees/vegetables etc.
- ☐ Repair/replacement of warning boards☐ TLP Box
- ☐ Pipeline protection net, Door & lock at Canal Crossing No 1, Error"

Checklist for T p r Business plaza

- ☒ Oil Leakage ☒ Encroachment
- ☐ Dumping of house construction materials.
- ☐ Wastages/Plastic bins ☐ Fire Incident
- ☐ TLP Box ☐ Repair / Replacement of Warning boards
- ☐ Cultivation of Banana trees/vegetables etc.
- ☐ Removal of trees branches ☐ Missing of Boundary pillars
- ☐ Pipeline protection net, Door & lock at Kaniyampuzha
- ☐ Removal of concrete pipe dumped on the pipeline"