Inspection Report

Property: Canada Line - SkyTrain, Metro Vancouver, BC, Canada
Inspection ID: 6a6f7b8246e345754f3c1e02
Type: maintenance
Date: Sat Aug 01 2026
Status: scheduled

Bedroom 1 (1/4)

Element	Images	Comment
Eeee	No images	-
See	No images	-
North window		north window looks fine
South Window	No images	-

Bathroom 1 (1/1)

Element	Images	Comment
bathtub		bath tub has mould on it

Garage 1 (0/0)

Element	Images	Comment

Bedroom2 (0/0)

Element	Images	Comment