



Incident ID: 6a22666e345b6807e47bc285 | Status: RESOLVED | Generated: 15/6/2026 | Verification: N/A

INCIDENT: Accident — Train Derailment

| SECTION 1      |  | EXECUTIVE SUMMARY                        |  |
|----------------|--|------------------------------------------|--|
| Incident ID    |  | 6a22666e345b6807e47bc285                 |  |
| Incident Type  |  | Accident                                 |  |
| Sub-Category   |  | Train Derailment                         |  |
| Severity Level |  | 2                                        |  |
| Location       |  | Lat: 19.170361, Lng: 72.95476            |  |
| Created At     |  | 5/6/2026, 11:32:22 am                    |  |
| Resolved At    |  | 5/6/2026, 11:35:45 am                    |  |
| Duration       |  | 3 min                                    |  |
| Summary        |  | Train Derailment reported at train 12454 |  |

| SECTION 2             |  | INCIDENT DETAILS         |  |
|-----------------------|--|--------------------------|--|
| Incident ID           |  | 6a22666e345b6807e47bc285 |  |
| Train Number          |  | 12454                    |  |
| Zone                  |  | Central Railway          |  |
| Division              |  | Mumbai CST               |  |
| Latitude              |  | 19.170361                |  |
| Longitude             |  | 72.95476                 |  |
| Severity              |  | 2                        |  |
| Incident Category     |  | Accident                 |  |
| Incident Sub-Category |  | Train Derailment         |  |
| Affected Component    |  | Multiple Coaches         |  |
| Mock Drill            |  | NO                       |  |
| Status                |  | RESOLVED                 |  |
| Created At            |  | 5/6/2026, 11:32:22 am    |  |
| Resolved At           |  | 5/6/2026, 11:35:45 am    |  |
| Duration              |  | 3 min                    |  |

| SECTION 3    |  | TRAIN & CREW DETAILS |  |
|--------------|--|----------------------|--|
| Train Number |  | 12454                |  |
| Train Name   |  | N/A                  |  |



# INDIAN RAILWAYS

Rapid Response Platform (R3P)

## INCIDENT INVESTIGATION REPORT



Incident ID: 6a22666e345b6807e47bc285 | Status: RESOLVED | Generated: 15/6/2026 | Verification: N/A

|                 |     |
|-----------------|-----|
| Train Direction | N/A |
|-----------------|-----|

| SECTION 4 | SUPERVISION DETAILS |
|-----------|---------------------|
|-----------|---------------------|

|                         |                  |
|-------------------------|------------------|
| Lead Supervisor         | N/A              |
| Lead Supervisor Emp. ID | N/A              |
| Lead Supervisor Contact | N/A              |
| Supervisor              | Aniruddha Sharma |
| Supervisor Emp. ID      | IRCRMUMSUP0001   |
| Supervisor Contact      | 8808011010       |

| SECTION 5 | RESOURCE DEPLOYMENT |
|-----------|---------------------|
|-----------|---------------------|

Total Operators Deployed: 0

| # | Operator Name | Emp ID | Designation | Duty | Accepted | Arrived | Done |
|---|---------------|--------|-------------|------|----------|---------|------|
|---|---------------|--------|-------------|------|----------|---------|------|

No operators deployed

| SECTION 6 | CASUALTY & IMPACT REPORT |
|-----------|--------------------------|
|-----------|--------------------------|

|                      |     |
|----------------------|-----|
| People Injured       | 0   |
| People Deceased      | 0   |
| Passengers Affected  | N/A |
| Staff Injured        | 0   |
| Staff Deceased       | 0   |
| Track Block Duration | N/A |
| Train Delays         | N/A |
| Property Damage      | N/A |
| Estimated Loss (Rs.) | N/A |

| SECTION 7 | INCIDENT TIMELINE |
|-----------|-------------------|
|-----------|-------------------|

Chronological sequence of events:

| # | Event             | Timestamp   | Elapsed | Remarks                |
|---|-------------------|-------------|---------|------------------------|
| 1 | Incident Created  | 11:32:22 am | 0 min   | Reported by supervisor |
| 2 | Incident Resolved | 11:35:45 am | 3 min   | Marked resolved        |

| SECTION 7B | OPERATOR RESPONSE LOGS |
|------------|------------------------|
|------------|------------------------|

### 7B.1 — Acceptance Log

| Operator | Notified At | Accepted At | Delay (min) | Status |
|----------|-------------|-------------|-------------|--------|
|----------|-------------|-------------|-------------|--------|

No log data



Incident ID: 6a22666e345b6807e47bc285 | Status: RESOLVED | Generated: 15/6/2026 | Verification: N/A

No response data

| SECTION 8                                                       | LOCATION & ROUTE ANALYSIS     |  |
|-----------------------------------------------------------------|-------------------------------|--|
| Incident Location                                               | Lat: 19.170361, Lng: 72.95476 |  |
| Incident GPS                                                    | 19.170361, 72.95476           |  |
| ART Train Location                                              | N/A                           |  |
| ART Train GPS                                                   | N/A                           |  |
| Distance Travelled                                              | N/A                           |  |
| Travel Time                                                     | N/A                           |  |
| Route map image not available — GPS coordinates recorded above. |                               |  |

| SECTION 9                            |  | EVIDENCE SUMMARY |                  |
|--------------------------------------|--|------------------|------------------|
| Evidence Type                        |  | Count            | Integrity Status |
| Photographs                          |  | 0                | VERIFIED         |
| Videos                               |  | 0                | VERIFIED         |
| Audio Recordings                     |  | 0                | VERIFIED         |
| Text Statements                      |  | 0                | VERIFIED         |
| Overall Evidence Integrity: VERIFIED |  |                  |                  |

| SECTION 10                   | TEXT STATEMENTS |
|------------------------------|-----------------|
| No text statements recorded. |                 |

| SECTION 11                         | PHOTOGRAPHIC EVIDENCE |
|------------------------------------|-----------------------|
| No photographic evidence recorded. |                       |

| SECTION 12                  | VIDEO EVIDENCE |
|-----------------------------|----------------|
| No video evidence recorded. |                |

| SECTION 13                  | AUDIO EVIDENCE |
|-----------------------------|----------------|
| No audio evidence recorded. |                |



**INDIAN RAILWAYS**  
Rapid Response Platform (R3P)  
**INCIDENT INVESTIGATION REPORT**



Incident ID: 6a22666e345b6807e47bc285 | Status: RESOLVED | Generated: 15/6/2026 | Verification: N/A

| SECTION 15        | CORRECTIVE ACTIONS                   |
|-------------------|--------------------------------------|
| Immediate Actions | Site secured, response team deployed |
| Temporary Actions | N/A                                  |
| Permanent Actions | N/A                                  |

| SECTION 16             | APPROVALS & SIGN-OFF   |                          |
|------------------------|------------------------|--------------------------|
| Prepared By            | Supervisor Approval    | Lead Supervisor Approval |
| Name: Aniruddha Sharma | Name: Aniruddha Sharma | Name: Pending            |
| Digital Signature:     | Digital Signature:     | Digital Signature:       |
| _____                  | _____                  | _____                    |

Report Generated: 15/6/2026, 1:06:33 pm

Digital Verification ID: 6a22666e345b6807e47bc285

