## **QUALITY CONTROL DASHBOARD**

2M

TotalProductionVolu...

2723

**TotalDefectiveUnits** 

3 15.32%

DefectRatePct

11.48

AvgMaintenanceHours

1.1K (33.83%) —

80.13

AvgQualityScore

0.30

AvgEnergyEfficiency

2.50%

AvgDowntimePct

3500

DefectStatus

□ o

7

Maintanence Fl...

High

Normal

Bin Energy Effic...

High

\_\_ Low

☐ Medium

**Defect Severity** 


\_\_ Low


Moderate


Severe


Supplier Delay ...

All











SupplierQuality	Low	Moderate	Severe	Total
80.00			1	1
80.00			1	1
80.01		1		1
80.01			1	1
80.02	1			1
80.03		1		1
Total	1096	1404	740	3240

## Count of Bin Energy Efficiency by DefectStatus





um of DefectRate	Bin Energy Efficiency	Sum of De
1,072.37	Medium	
1,005.96	Medium	
928.02	Medium	
724.87	Medium	
626.44	High	
8,907.14		