HotShots Automotive

Call : 303-617-1125 or Schedule Online at www.HotShotsAuto.com and view our Specials!

CUSTOMER NAME	VEHICLE	TECHNICIAN	DATE
DJPJ	13 NISSAN Murano	DEVON / TODD	10 / 8 / 26

	OK	A	B	C		OK	A	B	C
CONDITION OF ENGINE OIL	☒	☐	☐	☐	CONDITION OF POWER STEERING FLUID	☒	☐	☐	☐
CONDITION OF COOLANT	☐	☒	☐	☐	CONDITION OF BRAKE FLUID	☒	☐	☐	☐

	30-POINT COURTESY INSPECTION	CHECKED AND OK	(A) TOP PRIORITY	(B) SERVICE SOON	(C) RECOMMENDED MAINTENANCE	TECHNICIAN COMMENTS
1	DASHBOARD WARNING LIGHTS	☐	☒	☐	☐	P0081, P1217
2	A/C - HEATER OPERATION	☒	☐	☐	☐	
3	EMERGENCY BRAKE ADJUSTMENT	☒	☐	☐	☐	
4	EXTERIOR LIGHT OPERATION	☒	☐	☐	☐	
5	CONDITION OF WIPERS AND WASHER FLUID SYSTEM	☒	☐	☐	☐	
6	CONDITION OF DRIVE BELTS	☒	☐	☐	☐	
7	CONDITION OF RADIATOR AND HOSES	☐	☒	☐	☐	Radiator leaking
8	CONDITION OF HEATER HOSES	☒	☐	☐	☐	
9	CONDITION OF POWER STEERING PUMP AND HOSES	☒	☐	☐	☐	
10	CONDITION OF BATTERY AND CABLES	☒	☐	☐	☐	
11	CONDITION OF TUNE-UP COMPONENTS	☒	☐	☐	☐	
12	CONDITION OF FILTERS (AIR - CABIN & ENGINE, FUEL, PCV)	☒	☐	☐	☐	
13	CONDITION OF SHOCKS/STRUTS	☐	☒	☐	☐	Rough ride / rear shocks bad
14	FRONT BRAKE LININGS % WORN 8 mm	☒	☐	☐	☐	
15	REAR BRAKE LININGS % WORN 7 mm	☒	☐	☐	☐	
16	STEERING/SUSPENSION COMPONENTS	☒	☐	☐	☐	
17	TIRE CONDITION - LF 9/32 RF 8/32	☒	☐	☐	☐	
18	TIRE CONDITION - LR 10/32 RR 9/32	☒	☐	☐	☐	
19	WHEEL ALIGNMENT	☒	☐	☐	☐	
20	ENGINE LEAKS	☒	☐	☐	☐	
21	TRANSMISSION LEAKS	☒	☐	☐	☐	
22	DRIVETRAIN LEAKS	☒	☐	☐	☐	
23	AXLESHAFT / BOOTS / U-JOINTS	☒	☐	☐	☐	
24	MOTOR AND TRANSMISSION MOUNTS	☒	☐	☐	☐	

(OK) = CONDITION OF ITEM VISUALLY GOOD UNITL NEXT SERVICE INTERVAL. (A) = TOP PRIORITY - FIX IT NOW! (B) = SHOULD BE SERVICED/REPAIRED IN THE NEAR FUTURE. (C) PERFORM AS RECOMMENDED MAINTENANCE ON SCHEDULE