HotShots Automotive

Call : 303-617-1125 or Schedule Online at www.HotShotsAuto.com and view our Specials!

CUSTOMER NAME	VEHICLE	TECHNICIAN	DATE
HotShots	2014 Hyundai Elantra GT	DEVON / TODD	10 / 16 / 26

	OK	A	B	C
CONDITION OF ENGINE OIL	☑	☐	☐	☐
CONDITION OF COOLANT	☑	☐	☐	☐
CONDITION OF POWER STEERING FLUID	☑	☐	☐	☐
CONDITION OF BRAKE FLUID	☑	☐	☐	☐

30-POINT COURTESY INSPECTION	CHECKED AND OK	(A) TOP PRIORITY	(B) SERVICE SOON	(C) RECOMMENDED MAINTENANCE	TECHNICIAN COMMENTS
1 DASHBOARD WARNING LIGHTS	☑	☐	☐	☐	
2 A/C - HEATER OPERATION	☑	☐	☐	☐	
3 EMERGENCY BRAKE ADJUSTMENT	☑	☐	☐	☐	
4 EXTERIOR LIGHT OPERATION	☑	☐	☐	☐	
5 CONDITION OF WIPERS AND WASHER FLUID SYSTEM	☑	☐	☐	☐	
6 CONDITION OF DRIVE BELTS	☑	☐	☐	☐	
7 CONDITION OF RADIATOR AND HOSES	☑	☐	☐	☐	
8 CONDITION OF HEATER HOSES	☑	☐	☐	☐	
9 CONDITION OF POWER STEERING PUMP AND HOSES	☑	☐	☐	☐	
10 CONDITION OF BATTERY AND CABLES	☑	☐	☐	☐	
11 CONDITION OF TUNE-UP COMPONENTS	☑	☐	☐	☐	
12 CONDITION OF FILTERS (AIR - CABIN & ENGINE, FUEL, PCV)	☑	☐	☐	☐	
13 CONDITION OF SHOCKS/STRUTS	☑	☐	☐	☐	
14 FRONT BRAKE LININGS % WORN 9mms	☑	☐	☐	☐	
15 REAR BRAKE LININGS % WORN 9mms	☑	☐	☐	☐	
16 STEERING/SUSPENSION COMPONENTS	☑	☐	☐	☐	
17 TIRE CONDITION - LF 9 RF 9	☑	☐	☐	☐	
18 TIRE CONDITION - LR 9 RR 9	☑	☐	☐	☐	
19 WHEEL ALIGNMENT	☑	☐	☐	☐	
20 ENGINE LEAKS	☐	☐	☑	☐	0.1 pan seeping
21 TRANSMISSION LEAKS	☑	☐	☐	☐	
22 DRIVETRAIN LEAKS	☑	☐	☐	☐	
23 AXLESHAFT / BOOTS / U-JOINTS	☑	☐	☐	☐	
24 MOTOR AND TRANSMISSION MOUNTS	☑	☐	☐	☐	

(OK) = CONDITION OF ITEM VISUALLY GOOD UNITL NEXT SERVICE INTERVAL. (A) = TOP PRIORITY - FIX IT NOW! (B) = SHOULD BE SERVICED/REPAIRED IN THE NEAR FUTURE. (C) PERFORM AS RECOMMENDED MAINTENANCE ON SCHEDULE