HotShots Automotive

Call : 303-617-1125 or Schedule Online at www.HotShotsAuto.com and view our Specials!

CUSTOMER NAME	VEHICLE	TECHNICIAN	DATE
Hot Shots Sales	BMW 328ixDrGT	DEVON / TODD	11 / 10 / 26

	OK	A	B	C
CONDITION OF ENGINE OIL	☑	☐	☐	☐
CONDITION OF COOLANT	☐	☑	☐	☐
CONDITION OF POWER STEERING FLUID	☐	☐	☐	☐
CONDITION OF BRAKE FLUID	☑	☐	☐	☐

	30-POINT COURTESY INSPECTION	CHECKED AND OK	(A) TOP PRIORITY	(B) SERVICE SOON	(C) RECOMMENDED MAINTENANCE	TECHNICIAN COMMENTS
1	DASHBOARD WARNING LIGHTS	☑	☐	☐	☐	Has cold start roughness
2	A/C - HEATER OPERATION	☑	☐	☐	☐	
3	EMERGENCY BRAKE ADJUSTMENT	☑	☐	☐	☐	
4	EXTERIOR LIGHT OPERATION	☑	☐	☐	☐	
5	CONDITION OF WIPERS AND WASHER FLUID SYSTEM	☐	☐	☑	☐	Wipers streak
6	CONDITION OF DRIVE BELTS	☑	☐	☐	☐	
7	CONDITION OF RADIATOR AND HOSES	☐	☑	☐	☐	coolant hose patched
8	CONDITION OF HEATER HOSES	☑	☐	☐	☐	
9	CONDITION OF POWER STEERING PUMP AND HOSES	☐	☐	☐	☐	
10	CONDITION OF BATTERY AND CABLES	☑	☐	☐	☐	
11	CONDITION OF TUNE-UP COMPONENTS	☐	☐	☐	☑	Probably needs plugs
12	CONDITION OF FILTERS (AIR - CABIN & ENGINE, FUEL, PCV)	☑	☐	☐	☐	
13	CONDITION OF SHOCKS/STRUTS	☐	☑	☐	☐	leaking ~~both~~ all
14	FRONT BRAKE LININGS % WORN 11 mm	☑	☐	☐	☐	
15	REAR BRAKE LININGS % WORN 9 mm	☑	☐	☐	☐	
16	STEERING/SUSPENSION COMPONENTS	☑	☐	☐	☐	
17	TIRE CONDITION - LF 5/32 RF 5/32	☐	☐	☐	☐	
18	TIRE CONDITION - LR 4/32 RR 4/32	☐	☐	☐	☐	
19	WHEEL ALIGNMENT	☐	☐	☐	☑	
20	ENGINE LEAKS	☑	☐	☐	☐	
21	TRANSMISSION LEAKS	☑	☐	☐	☐	
22	DRIVETRAIN LEAKS	☑	☐	☐	☐	
23	AXLESHAFT / BOOTS / U-JOINTS	☑	☐	☐	☐	
24	MOTOR AND TRANSMISSION MOUNTS	☐	☑	☐	☐	Engine Mounts sagging

(OK) = CONDITION OF ITEM VISUALLY GOOD UNITL NEXT SERVICE INTERVAL. (A) = TOP PRIORITY - FIX IT NOW! (B) = SHOULD BE SERVICED/REPAIRED IN THE NEAR FUTURE. (C) PERFORM AS RECOMMENDED MAINTENANCE ON SCHEDULE