



Care Net Consultants (Pty) Ltd
Reg no: 2012 / 038468 / 07
VAT no: 4620265191

 www.carenetconsultants.co.za
 +27 60 070 2723
 salesdesk@carenetconsultants.co.za
 154 Allan Road, Midrand 1684



EXAMPLE DOCUMENT. Kornetvale Agri Logistics (Pty) Ltd is a fictitious company. Every company, person, address, date, figure and reference number in this example is made up; only the Care Net letterhead and any public emergency number are real. For guidance only; not a document to sign or rely on.

Example for a Health and Safety File, Section M: Environment, welfare and facilities

Welfare and Facilities Inspection Checklist

Annual inspection of the Bloemfontein depot, 11 May 2026

About this example	Detail
Company in the example	Kornetvale Agri Logistics (Pty) Ltd, a fictitious company
Where it is filed	Section M: Environment, welfare and facilities
Published by	Care Net Consultants, as guidance for companies building a Health and Safety File

How to use this example


This example shows the form and content Care Net recommends for this document in a Health and Safety File. Adapt it to your company, your sites and your appointments; your registered Health and Safety practitioner confirms it before your File is released. Not legal advice.

Contents

1. Inspection details
2. Checklist
3. Findings and corrective actions
4. Close out



YOUR PARTNER IN WORKPLACE HEALTH.



Welfare and Facilities Inspection Checklist

Annual inspection of the Bloemfontein depot, 11 May 2026


1. Inspection details

Item	Detail
Site	Bloemfontein depot, 9 Kameeldoring Street, Hamilton, Bloemfontein
Employees on site	38 (29 men, 9 women) over two shifts
Inspected by	Karabo Mokoena, Health and Safety Officer, with Elna Botha, health and safety representative
Date	Monday 11 May 2026, 08:00 to 10:30
Previous inspection	12 May 2025; all findings closed

Each item is marked **Yes** (in order), **No** (a finding) or **N/A**. Numbers of toilets, basins and showers and the lighting and ventilation levels are checked against what the applicable regulations and your risk assessment set; where you are unsure, ask your registered Health and Safety practitioner.

2. Checklist

Area	What we checked	Result	Finding
Sanitation	Separate, clean, lockable toilets for men and women, with paper, soap and hand drying	Yes	In order
Sanitation	Enough toilets and basins for the number of employees on the largest shift	Yes	In order
Sanitation	Sanitary bins in the women's toilets, emptied by the service provider	No	Service record for April missing
Drinking water	Clean drinking water close to work areas, with cups or a fountain	Yes	In order
Changing rooms	Separate changing rooms with lockers and seating	Yes	In order
Changing rooms	Showers working with hot and cold water	No	One of three showers in the men's room has no hot water



Area	What we checked	Result	Finding
Eating areas	A clean eating area away from the loading bay, with tables, seating, a fridge and a way to heat food	Yes	In order
Eating areas	No food or drink in the chemical store or the workshop	Yes	In order
Lighting	Lighting in the warehouse aisles, loading bay and yard is good enough for the tasks	No	Two lamps out in aisle 4
Lighting	Emergency lighting works on the escape routes	Yes	Tested on the day
Ventilation	Workshop and battery charging bay ventilated, extraction fan working	Yes	In order
Ventilation	Offices and eating area have openable windows or working air conditioning	Yes	In order
Waste	General waste in closed bins, removed by the municipal service	Yes	In order
Waste	Used oil, oily rags and fluorescent tubes kept apart and removed by a licensed contractor with a manifest	No	Last waste manifest not on file

3. Findings and corrective actions

No.	Finding	Action	Owner	Due
1	Sanitary bin service record for April missing	Obtain the record from the service provider and file it	Elna Botha	15/05/2026
2	No hot water in one shower	Repair the geyser valve	Willem Nel	18/05/2026
3	Two lamps out in aisle 4	Replace the lamps and add aisle lighting to the weekly check	Willem Nel	13/05/2026
4	Last waste manifest not on file	Obtain the manifest from the waste contractor and file it	Karabo Mokoena	22/05/2026

4. Close out

The inspector checks each action on its due date and signs it off in the corrective action log. The next full inspection is due in May 2027, or earlier if the depot changes its layout or its number of employees.



Health and Safety Officer

Karabo Mokoena, Date: _____

Health and safety representative

Elna Botha, Date: _____

Depot Manager (appointed under section 16(2))

Hendrik Coetzee, Date: _____

End of the example. The company, people and records in it are fictitious; the cover page explains how to use it.



YOUR PARTNER IN WORKPLACE HEALTH.

