

PMT SERVICE AND MAINTENANCE REPORT

CLIENT DETAIL

TOP GLOVE F31	Report Date	7/3/2026	Report Number	MIT-2025-61
JALAN PELABURAN 15A, BATU 5 1/2, 42200 KAPAR, SELANGOR	Service Date	6/3/2026	Service By	Team 1 (T.M)
	CF Expired Date	N/A	Client Incharge	SYAFIQ

PMT No	N/A	Manufacturer	TONG CHENG IRON WORKS CO. LTD		
Serial No	A17071205	Year Built	2016	MAWP (Psi)	164
Vessel Type	HORIZONTAL	Safety Valve Size	N/A	Volume (Litre)	N/A

SCOPE OF MAINTENANCE		STATUS	REMARK
1	External Physical condition service: Cleaning all the visual dirt, grease, dust and etc to the satisfied end (<i>as far as practicable</i>).	√	
2	Internal Vessel Service: Cleans all the dirt, oil, water, impurities and etc (<i>as far as practicable</i>). Check for internal corrosion. Touch up with anti-corrosion paint if possible. If not, perform internal boroscope inspection for evaluation.	√	
3	Safety valve testing: Testing the safety valve functioning manually and in- operation testing at its setting value. Perform calibration check as per TMSB calibration procedure	√	SET AT 10 BAR
4	Draining Valve: Ensure valve is functioning and able to drains the vessel appropriately	√	
5	Pressure Gauge: ' Zero value ' at emptied vessel, marking at MAWP value as designed by manufacturer. Perform calibration check as per TMSB calibration procedure	√	TO MARK MAWP ON GAUGE
6	Testing & commissioning: Running the whole system to ensure all parts and system in good shape & works evidently	N/A	
7	Saddle, leg or foundation condition	√	
8	Nozzle/ flange connection and insulation condition	√	

COMMENT & RECOMMENDATION

1	Pull the safety valve regularly to avoid malfunction. Contact us promptly in the event of failure. Required to calibrate safety valve and pressure gauge
2	

SUMMARY

- Keep this report for record and references.

SERVICES & MAINTENANCE PROCESS

APPENDIX PICTURE

COMPRESSOR NAME PLATE AND OVERALL VISUAL



INTERNAL PHOTO



	Review and approved by
 TIJARAH MABRUR (M) SDN BHD Registered: 202201023780 (1469477-U) F-6-8, Setapak Commercial Centre (Starpac Point) Jalan Taman Ibu Kota, Taman Danau Kota, 53100, Setapak Kuala Lumpur, Malaysia. Office: +60341444035 Whatsapp: +60123983404 Email: admin@tjrahmabrur.my Website: www.tjrahmabrur.my Syukri Yusof Crane & Machinery inspector - NIOSH Tijarah Mabrur (M) Sdn Bhd Mobile : 017-5998433 Email: syukri@tjrahmabrur.my	 TIJARAH MABRUR (M) SDN BHD Registered: 202201023780 (1469477-U) F-6-8, Setapak Commercial Centre (Starpac Point) Jalan Taman Ibu Kota, Taman Danau Kota, 53100, Setapak Kuala Lumpur, Malaysia. Office: +60341444035 Whatsapp: +60123983404 Email: admin@tjrahmabrur.my Website: www.tjrahmabrur.my Shalihin Idris Consultant, Safety & Health Advisor-NIOSH Cert NDT Inspector, Ultrasonic Thickness Gauging (UTG) Level II-SIRIM/JPK Mobile : 012-3983404 Email: shalihin@tjrahmabrur.my

END OF REPORT