

FORM REPORT BARCODING MATERIAL LUMPUR

Date : 2021-10-05

Job Order From : Barcoding material lumpur

No. OAS/Contract : 12345

Services : Elnusa

Verificator : Andhika Rizky

QAQC :.....

Inspection : Barcoding material lumpur

Location Inspection: medan

	Description	Observation			Remarks			Recomm	
No	Equipment/Services/Personel	Refference	Result	Comment	Followup	SN	Picture	Ok/Not	PIC
1	Chemical								
а	Barite	Manufacturer	Ok	Ok	Ok	2014	TOCHTON I. Edward on Manager J. Bellow the	OK	Ok

	Description	Observation			Remarks			Recomm	
No	Equipment/Services/Personel	Refference	Result	Comment	Followup	SN	Picture	Ok/Not	PIC
b	Barite	Manu	Ok	Ok	Ok	2019	VE SE SHOOL 1 Control Manager 1 Consylvation 2 Consylvation 1 Consylvation 2 Consylvation 2 Consylvation 3 Consylvation 4 Construction 5 Construction 6 Construction 6 Construction 7 Construction 6 Construction 7 Construction 7 Construction 8 Construction	Ok	Ok
С	Barite	Manu	Ok	Ok	Ok	2017	POSITION IL Editoritor Munique I Editoritor Munique I Editoritor Munique I Editoritor Munique I Editoritoritor I Manager I Ma	Ok	Ok
d	KCL	Manuf	Ok	Ok	Ok	4681	POSITION 1. Extention Manager 2. Sensign of the CRE WARD 4. Office Report of General Appendix of CRE WARD 5. Personal in Stream of General Appendix of CRE WARD 6. Need Core Report of General Appendix of CRE WARD 6. Sect Condition of Manager 6. Sect Condition of Manager	OK	Ok

Note

Done

Wittness By,

Copyright © Pertamina EP 2021 05-Oct-2021, All Right Reserved

Andhika Rizky

Lilik Supriyanto