


FORM REPORT INSPECTION

Date : 2021-09-17
Job Order From : Inspection
No. OAS/Contract :
Services : Schlumberger
Inspector : Gatot Teguh
QAQC :
Inspection : Inspection
Location Inspection : Cikarang

No	Description	Observation			Remarks			Recomm	PIC
	Equipment/Services/Personel	Reference	Result	Comment	Followup	SN	Picture	Ok/Not	
1	Mud motor								
a	Mud motor	DS1 CAT3-4	No issue	Ready..	-	5678		Ok	Rendyza

Note

Witness By,



Gatot Teguh



Link Supriyanto