

Date:09/09/2022 06:13AM

Post Scan

Vehicle Sysytem Report

Vehicle Information

MAKE Chevrolet
YEAR 2019
MODEL Traverse (FWD)
ENGINE 3.6L V6 (LFY)
SYSTEM CodeScan
BEN

CODE SCAN RESULTS

Systems Analyzed:16

- ✔ Engine: 0
- ⚠ Transmission: 1
- ✔ Antilock Brakes: 0
- ✔ Airbag: 0
- ✔ Body Control Module: 0
- ✔ HVAC: 0
- ✔ HVAC Controls: 0
- ✔ Instrument Panel Cluster: 0
- ✔ Keyless Entry: 0
- ✔ Passenger Presence System: 0
- ✔ Power Steering Control Module: 0
- ✔ Radio: 0
- ✔ Serial Data Gateway Module: 0
- ✔ Serial Data Gateway Module: 0
- ✔ Telematics Communication Interface: 0
- ✔ Tire Pressure Monitor: 0
- ✔ OBDII Codes (\$03): 0
- ✔ OBDII Permanent Codes (\$0A): 0

Transmission

P0826 | Up and Down Shift Switch Circuit (Symptom 00) - Test Failed Since DTC Clear, History DTC, Test Not Passed Since Power Up.

Readiness Monitors

Tests Complete

- ✔ Misfire
- ✔ Fuel System
- ✔ Comprehensive Component
- ✔ EGR/VVT
- ✔ Catalyst
- ✔ Evaporative System
- ✔ Oxygen Sensor
- ✔ Oxygen Sensor Heater