

Date:09/01/2022 06:28AM

Post Scan

Vehicle Sysytem Report

Vehicle Information

MAKE Hyundai
YEAR 2021
MODEL Elantra
ENGINE 1.6T GDI GAMMA II
SYSTEM CodeScan
BEN

CODE SCAN RESULTS

Systems Analyzed:16

- ✔ Engine: 0
- ✔ Transmission: 0
- ⚠ Antilock Brakes: 1
- ✔ Airbag: 0
- ✔ Body Control Module: 0
- ✔ Cluster Module: 0
- ✔ Electronic Power Steering: 0
- ⚠ Front View Camera: 2
- ✔ Immobilizer: 0
- ✔ Integrated Central Control Unit: 0
- ⚠ Rear Corner Radar: 1
- ⚠ Rear Corner Radar: 1
- ✔ Rear View Monitor: 0
- ✔ Smart Key Unit: 0
- ✔ Tire Pressure Monitor: 0
- ✔ Weight Classification: 0
- ✔ OBDII Codes (\$03): 0
- ✔ OBDII Permanent Codes (\$0A): 0

Antilock Brakes

C126402 | Pump Motor Electrical

Front View Camera

C272246 | System out of Calibration
C164202 | CAN Message Failure - Brake

Rear Corner Radar

C169381 | CAN Message Failure - ESC

Rear Corner Radar

C169381 | CAN Message Failure - ESC

Readiness Monitors

Tests Complete

- ✔ Misfire
- ✔ Fuel System
- ✔ Comprehensive Component
- ✔ EGR/VVT
- ✔ Catalyst
- ✔ Evaporative System
- ✔ Oxygen Sensor
- ✔ Oxygen Sensor Heater