Request Information

ID: 66308de65e6f722a02b759b7

Form ID: DN-0002 Date: 11/04/2024

Description: Replacing damaged roofing materials in dog

enclosures.
Amount: 3100



Request Information

ID: 66308dfb5e6f722a02b759ba

Form ID: DN-0003 Date: 11/04/2024

Description: Scheduled maintenance for dog cage shelter

roofs.

Amount: 3100



Request Information

ID: 66308e045e6f722a02b759bc

Form ID: DN-0004 Date: 11/04/2024

Description: Repairing leaks and ensuring structural integrity

of dog shelter roofs.

Amount: 3100



Request Information

about:srcdoc Page 1 of 2

ID: 66308e0c5e6f722a02b759be

Form ID: DN-0005 Date: 11/04/2024

Description: Roof maintenance for dog enclosures to ensure

safety and comfort.

Amount: 3100



Request Information

ID: 66308e145e6f722a02b759c0

Form ID: DN-0006 Date: 11/04/2024

Description: Ensuring proper drainage and waterproofing for

dog cage roofs. Amount: 3100 Accept Reject