

Annexure D

BUILDING SAFETY CERTIFICATE

No. 1034

Dated: 26/04/2026

It is certified that the existing building **NIIST PUBLIC SCHOOL**, (name of the building or premises) **At/Po- Barimunda, Ps- Mancheswar, Dist- Khordha, Odisha 754001** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2					

The building is owned/occupied by **NIIST PUBLIC SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R & B Sub- Division, Bhubaneswar** (Name of Department/Govt.) on **11/03/2026** (date of inspection) in the presence of **Mrs. Swarna Rekha Parija**, Bhubaneswar (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **26/04/2026** for a period of **02** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Roof top should be clean in every one year
2. External and internal walls are crack-free and well-maintained

Issued on **26/04/2026** at **Bhubaneswar** by



Asst. Executive Engineer

Bhubaneswar (R&B) Sub-Division

Prahallad Ratha

Asst. Executive Engineer

R & B Sub- Division

Bhubaneswar