Annexure D

BUILDING SAFETY CERTIFICATE

No. 036 **Dated: 22/01/2026**

It is certified that the existing building **Pearly International School,** (name of the building or premises) **At- Jagannath Nagar, Po- GGP, Ps- Laxmisagar, Dist- Khordha, Odisha** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1					

The building is owned/occupied by **Pearly International School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R & B Sub- Division, Bhubaneswar** (Name of Department/Govt.) on **07/01/2026** (date of inspection) in the presence of **Sushree Sangita Priyadarshinee**, Bhubaneswar (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **22/01/2026** for a period of **03** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Roof top should be clean in every one year
2. External and internal walls are crack-free and well-maintained

Issued on **22/01/2026** at **Bhubaneswar** by

22/01/26
Asst. Executive Engineer
Bhubaneswar (R&B) Sub-Division

Asst. Executive Engineer
R & B Sub- Division
Bhubaneswar

Digitally signed by RABINDRA NATH KAR
Date: 2026.09.29 00:33:46 +05:30
Reason: reason
Location: location