

BUILDING SAFETY & BUILT-UP AREA CERTIFICATE

Certificate No.: PIS/0412/2026

Date: 17/04/2026

This is to certify that I have personally inspected the school building premises of **Petals International School**, situated at **At-Brahmanjharilo, Po-Kusakanta, Ps-Kuranga, Dist.-Cuttack, Odisha, 754001** and verified the building plans, measurements, and structural details of the institution.

Based on the physical inspection and submitted documents, it is certified that the school building has the following built-up area and infrastructure details:

Sl.No.	Particulars	Details
1	Name of the School	<u>Petals International School</u>
2	Address of the School	<u>Brahmanjharilo, Kusakanta, Kuranga, Cuttack, Odisha, 754001</u>
3	Total Land Area	<u>11816.82 Sq. Mtr.</u>
4	Total Built-up Area	<u>4202.19 Sq. Mtr.</u>
5	Number of Floors	<u>G+1</u>
6	Number of Classrooms	<u>47</u>
7	Size of Classrooms	More than <u>556</u> Sq. Ft. each
8	Laboratories Available	Yes
9	Library Facility	Yes
10	Administrative Block	Yes
11	Toilets & Sanitation	Adequate
12	Fire Safety Provisions	Available
13	Staircases & Ventilation	Adequate

Further certified that the school building is constructed as per approved plan and the available built-up area fulfills the norms and infrastructure requirements prescribed by Central Board of Secondary Education for affiliation purposes.

The structure appears safe and suitable for running educational activities for students.

DETAILS OF ARCHITECT / ENGINEER

Name: Ms Nandini Ghosh

Registration No.: CA/2016/80295

Designation: Licensed Architect / Civil Engineer

Nandini Ghosh
Signature of Architect

