

Annexure D

BUILDING SAFETY CERTIFICATE

No. 180/2026

Dated: 17/05/2026

It is certified that the existing building **Venkateswar School**, (name of the building or premises) **At- Rairangpur, Mayurbhanj, Odisha** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2					

The building is owned/occupied by **Venkateswar School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R & B Sub- Division** (Name of Department/Govt.) on **05/05/2026** (date of inspection) in the presence of **Mrs. Jayanti Naik, Rairangpur** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **17/05/2026** for a period of **02** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Emergency exits must be clearly marked and easily accessible.
2. Staircases shall be wide, well-lit, and provided with handrails.
3. The building shall have fire-resistant construction materials wherever applicable.

Issued on **17/05/2026** at **Rairangpur** by


Asst. Executive Engineer
Rairangpur (R & B) Sub-Division
R & B Sub- Division
Rairangpur