

Condition Report

2022 LEXUS ES ES 350

58ADZ1B17NU117484 • Odo 19,966
Black / Black • 6-Cylinder • AUTOMATIC • Front Wheel Drive

BEAVER TOYOTA OF CUMMING



Announcements

Remarks/Comments

Title

TITLE STATE

TITLE STATUS

NOT SPECIFIED

Issues

DRIVABILITY, KEYS, & HISTORY	0
EXTERIOR	3
INTERIOR	0
MECHANICAL & DIAGNOSTIC TROUBLE CODES	1
TIRES & WHEELS	1

INSPECTION

Drivability, Keys, & History

SMART KEYS
1

OTHER KEYS
0

ODOR/BIO/ENVIRONMENTAL/HISTORY
None

VEHICLE STARTS
Yes - Starts



VEHICLE DRIVES
Yes - Drives

Exterior

FRONT EXTERIOR

! FRONT BUMPER

Paint Chipped

! FRONT HOOD

Paint Chipped

DRIVER EXTERIOR

No Damage

ROOF - EXTERIOR

No Damage

REAR EXTERIOR

No Damage

PASSENGER EXTERIOR

! PASSENGER QUARTER

Small Dent

FURTHER DISCLOSURES

Not Specified

Interior

AIRBAGS

No Issues

INFOTAINMENT/RADIO

Fully Functional

CLIMATE CONTROL

Fully Functional

SUNROOF OPERATION

Fully Functional

ELECTRICAL ACCESSORY

Fully Functional

INTERIOR COSMETIC DAMAGE

No Damage

Mechanical & Diagnostic Trouble Codes

DIAGNOSTIC TROUBLE CODES

No Active Codes

WARNING LIGHTS & GAUGE CLUSTER

! WARNING LIGHTS & INFO SCREEN

Blind Spot Monitor

VEHICLE SMOKE

No Issues

EMISSIONS/CATALYTIC/EXHAUST

Factory Equipment Installed

ACTIVE VISIBLE LEAKS FROM ENGINE OR UNDERCARRIAGE AREA

No Active Leaks

ENGINE NOISE

No Issues

ENGINE OIL SLUDGE

No Oil Sludge

OTHER MECHANICAL COMMENTS

Not Specified

1

SUSPENSION MODIFICATION

None

Tires & Wheels

DRIVER FRONT TIRE DEPTH
6/32" or Above

DRIVER FRONT TIRE & WHEEL ISSUE
No Issues

DRIVER REAR TIRE DEPTH
6/32" or Above

DRIVER REAR TIRE & WHEEL ISSUE
No Issues

PASSENGER REAR TIRE DEPTH
6/32" or Above

PASSENGER REAR TIRE & WHEEL ISSUE
No Issues

PASSENGER FRONT TIRE DEPTH
6/32" or Above

! PASSENGER FRONT TIRE & WHEEL ISSUE
Wheel Cosmetic Damage

 Contact Client Care

 866-626-4346

[Visitor Agreement](#) • [Privacy Policy](#) • [Marketplace Policy](#)