AUTOMATED SURVEYING

Atutomated Survey Report on ProjectZero

To View The report pdf Click Here.

Extent of Survey: 5.0

Number of Images Captured: 2

Vegetation Report

Image Number
NDVI Output
Image Area Details

1 0 0 1

Failed to load

Height of Capture: 2 0 . 0 m

Area Covered: 8 4 4 . 5 8 2 4 7 2 0 0 0 6 7 3 1 m²

Area Under Green Cover: 1 1 1 1 . 7 4 9 2 0 8 2 5 3 2 0 5 3 m²

1 0 0 2

Failed to load

• Height of Capture: 1 5 . 0 m

Area Covered: 4 7 5 . 0 7 7 6 4 0 5 0 0 3 7 8 6 m²

Area Under Green Cover: 1 7 9 . 4 2 2 7 0 9 3 5 0 9 6 5 4 5 m²

Settlement Report

Image Number
Original Image

Settlement Segmented Image

Image Area Details

1 0 0 1

Failed to load

Failed to load

Height of Capture: 2 0 . 0 m

Area Covered: 8 4 4 . 5 8 2 4 7 2 0 0 0 6 7 3 1 m²

Area Under Settlement: 7 7 . 0 9 1 8 6 3 2 1 2 7 0 7 9 2 m²

1 0 0 2

Failed to load

Failed to load

• Height of Capture: 1 5 . 0 m

Area Covered: 4 7 5.0 7 7 6 4 0 5 0 0 3 7 8 6 m²

Area Under Settlement: 1 8 6 . 5 3 4 0 8 5 7 7 5 0 8 1 5 m²

Water Cover Report

Image Number
Original Image
Water Body Segmented Image
Image Area Details

1 0 0 1

Failed to load

Failed to load

Height of Capture: 2 0 . 0 m
 Area Covered: 8 4 4 . 5 8 2 4 7 2 0 0 0 6 7 3 1 m²
 Area Under WaterBody: 3 3 3 . 2 2 7 0 6 5 7 1 2 3 0 1 7 m²

1 0 0 2

Failed to load

Failed to load

Height of Capture: 1 5 . 0 m

Area Covered: 4 7 5 . 0 7 7 6 4 0 5 0 0 3 7 8 6 m²
 Area Under WaterBody: 3 3 . 5 7 7 8 7 5 2 2 5 7 9 5 8 m²