


Atutomated Survey Report on projectDemo

To View The report pdf [Click Here.](#)

Extent of Survey : 5.0  
Number of Images Captured : 2


Vegetation Report

Image Number  
NDVI Output  
Image Area Details  
7001



- Height of Capture: 20.0 m
- Area Covered: 844.5824720006731 m<sup>2</sup>
- Area Under Green Cover: 755.1445698448401 m<sup>2</sup>

7002



- Height of Capture: 20.0 m
- Area Covered: 844.5824720006731 m<sup>2</sup>
- Area Under Green Cover: 411.95561675984976 m<sup>2</sup>

Settlement Report

Image Number  
Original Image  
Settlement Segmented Image  
Image Area Details  
7001



Height of Capture: 20.0 m

Area Covered: 844.5824720006731 m<sup>2</sup>

Area Under Settlement: 143.98986754857665 m<sup>2</sup>



Height of Capture: 20.0 m

Area Covered: 844.5824720006731 m<sup>2</sup>

Area Under Settlement: 654.6364720187102 m<sup>2</sup>

- 
- 
- 

## Water Cover Report

Image Number  
Original Image  
Water Body Segmented Image  
Image Area Details

7001





Height of Capture: 20.0 m

Area Covered: 844.5824720006731 m<sup>2</sup>

Area Under WaterBody: 618.4875792885788 m<sup>2</sup>



Height of Capture: 20.0 m

Area Covered: 844.5824720006731 m<sup>2</sup>

Area Under WaterBody: 355.0581617140281 m<sup>2</sup>

- 
- 
-