



FML FREIGHT SOLUTIONS
SERVICE DRIVEN SOLUTIONS

Ref: BA 2797

BARTRAC INSPECTION LIST

Page 1 of 2

DESCRIPTION:	BOND ARRIVAL DATE:	FMLREF NO:
1x CAT 428-07A Backhoe Loader	29/10/2024	2410 DSI 2607
VIN NO: SERIAL NO: -	ENGINE NO:	SERIAL NO: VIN NO: -
L7D001960	C4Z14718	CAT00428KL7D01960

EXTERIOR	
BUCKET - FRONT	Scratches to underside of bucket from arrival
BUCKET - REAR	In order - nested in front bucket
BACKHOE	In order
HYDRAULI RAMS - FRONT	In order
HYDRALIC RAMS - REAR	In order
LOAD BIN	N/A
CAB	All in order - locked again after inspection
COUNTERWEIGHT	N/A
RIGHT FRONT	} All in order
LEFT FRONT	
RIGHT REAR	
LEFT REAR	
RIGHT SIDE	



FML FREIGHT SOLUTIONS
SERVICE DRIVEN SOLUTIONS

Ref: BA 2797

BARTRAC INSPECTION LIST

Page 2 of 2

LEFT SIDE	All in order
WHEELS/TRACKS	All in order
STARTING STATUS	Battery removed for safe keep and improved starting functionality.
INTERIOR	
CAB	All in order
BATTERY BAY	Battery stored in container. Sealed package within - presume tools
ENGINE BAY	All in order

GENERAL COMMENTS RELATING TO OVERALL CONDITION OF THE MACHINE :-
Other than mentioned scratches and general transit & storing dirt & grime, machine is in excellent condition.

BOND STORE REF :	NAME :	SIGNATURE :	INSPECTION DATE :
2410-100000059	Vince Foulis		22/04/2025