# HALDEN RIDGE STEEL

Plate Division · 4100 Furnace Road

## MILL TEST REPORT

EN 10204 Type 3.1

| CERTIFICATE NO. | DATE | CUSTOMER P.O. |
|---|---|---|
| HR-88213 | 09/14/2026 | 2417-0031 |
| **SPECIFICATION** | **PRODUCT** | **HEAT NO.** |
| ASME SA-516 GR 70 | PLATE, NORMALIZED | N48213 |
| **THICKNESS (IN)** | **WIDTH x LENGTH (IN)** | **PIECES** |
| 1.000 | 96 x 240 | 2 |

### CHEMICAL ANALYSIS (HEAT) – WEIGHT %

| C | MN | P | S | SI | CU | NI | CR |
|---|---|---|---|---|---|---|---|
| .22 | 1.08 | .012 | .004 | .25 | .03 | .02 | .04 |

### TENSILE TEST

| YIELD (KSI) | TENSILE (KSI) | ELONG % IN 2 IN | DIRECTION |
|---|---|---|---|
| 52.1 | 78.5 | 24 | TRANSVERSE |

We hereby certify that the material described above has been manufactured and tested in accordance with the specification shown and that the results meet its requirements.

Quality Assurance Manager

SAMPLE DOCUMENT. Fictional mill and fictional data, made for a software demonstration.