

## Foodstuffs Parts Return

Job Details:	
Engineer:	Jarred Green
Date:	03-04-16
Job Number (SV):	SV1603220044
Site Name:	PK Thames
Pa GNU	art Status (Please Circle):  Faulty  Installed Part:
Installed Part Number:	ilistalieu Fart.
Installed Part Description:	
Installed Serial Number:	046133
Installed Asset Tag:	
Faulty Part:	
Faulty Part Number:	
Faulty Part Description:	
Faulty Serial Number:	046025
Faulty Asset Tag:	
	Fault Description:

Base unit was running slowly. Rebuilt and tested. Lane has some weird config, uses id of lane 18 instead of	
17 and hand scanner. Tested eftpos, printer, scanner and cashdrawer. All working. Nick from foodstuffs sys	
admin had to do some updates.	