



SOLOMON

KINGS VALLEY OPERATIONS

DATE: 18 NOV 2019

## 5 Why Worksheet

### EVENT DESCRIPTION

On 25/03/2022, Side plate crack



### CAUSE

**Cause:** Side plate crack**Evidence:** evidence

### CAUSE

**Cause:** Split node**Evidence:** Split node

### CAUSE

**Cause:** Split node**Evidence:** Split node

### CAUSE

**Cause:** Split node**Evidence:** Split node

### SOLUTIONS

#### ACTION

This is what should be done

#### WHO

User name

#### WHEN

12/12/2012

### GROUP PARTICIPANTS

Benjamin Hislop

Campbell Beck

Johann Row

Robert Hanning

### SUPERVISOR

**Name:** James White**Sign:****Date:**