

Service report

North Studio 1791353973524 · Bandung · Second floor

INVOICE REFERENCE	REVISION
INV-2026-008	1
TECHNICIAN ACCOUNT	APPROVED BY
tech1791353973524	owner · Oct 7, 2026, 6:19:38 AM

Lobby · AC-01

✓ Cleaned ✓ Drain checked ✓ Cooling checked

Cleaned coil and filter; flushed drain. Outlet temperature: 17 °C.



Before service



After service