

Service report

North Studio · Bandung · Second floor

INVOICE REFERENCE	REVISION	TECHNICIAN ACCOUNT	APPROVED BY
INV-2026-008	1	alex_050043	owner · Oct 7, 2026, 6:54:15 AM

Lobby · AC-01

✓ Cleaned ✓ Drain checked ✓ Cooling checked

Cleaned coil and filter; flushed drain. Outlet temperature: 17 °C.



BEFORE SERVICE



AFTER SERVICE

Job 91ec99a1-2ce7-490a-a4f1-52c9e8e04e6c · Revision 1
This record documents submitted service evidence. Photos are not tamper-proof; account identities are not independently verified. This is an invoice attachment, not an invoice.

