



Category	Details
Project Name	x
Project ID	x
Project Location	x
Company Name	ICoM GmbH
Inspector Name	Max Mastermann
Date of Inspection	02/04/2025
Damage & Object Type(s)	Graffiti, PEquipment (Protective Equipment)
Impact	There is no visible damage to the structure or any equipment.
Size	0.00 cm <sup>2</sup> (if applicable)
Direction	Horizontal (along the length of the bridge)
Possible Reasons	The graffiti could have been caused by unauthorized markings or markings made by vehicles, which may have led to minor damage to the bridge structure or equipment.