



Category	Details
Project Name	x
Project ID	x
Project Location	x
Company Name	ICoM GmbH
Inspector Name	Max Mastermann
Date of Inspection	02/04/2025
Damage & Object Type(s)	Spalling, Weathering, PEquipment (Protective Equipment), Rust
Impact	Weathering and rust staining on the concrete surface, possibly due to prolonged exposure to the elements.
Size	0.01 cm ²
Direction	Horizontal
Possible Reasons	Exposure to the elements, lack of protection, environmental conditions, and potential for rust to spread over time.