



# Compliance Audit Report

**Client Name:** EnergyCorp

**Location:** South China Sea oil rig #10120

**Date:** 09/01/2020

CATEGORY	SUBCATEGORY	%	COMPLIANCE BAND	COMMENTS
PLANT	Condition Based Maintenance	43	Minor Non-Compliance	Lorem ipsum garbage
	Cost of Ownership	78	Top Quartile	Lorem ipsum garbage
	Overall Equip. Condition	51	Compliant	Lorem ipsum garbage
PEOPLE	Continuous Improvement	26	Minor non-Compliance	Lorem ipsum garbage
	Communication	87	Top	Lorem ipsum garbage
	Competency & Skills	89	Top Quartile	Lorem ipsum garbage
PROCESS	Document Management	45	Minor non-Compliance	Lorem ipsum garbage
	Integrated Act. Planning	29	Minor non-Compliance	Lorem ipsum garbage
	Logistics	76	Top Quartile	Lorem ipsum garbage
PRODUCTION	Forecasting	56	Compliant	Lorem ipsum garbage
	Hydrocarbon Management	67	Compliant	Lorem ipsum garbage
	Production Programming	77	Top Quartile	Lorem ipsum garbage