



CRANE INSPECTION & MAINTENANCE SERVICES

A DIVISION OF AL-KHOBAR GATE INTERNATIONAL TRADING EST

INSPECTION CHECKLIST FOR FORK LIFT

FRM.0601-1.15

Revision 00

Issue Date: 01/JAN/2020

Prepared By
Operations Manager

Reviewed & Approved By
Managing Director



	CRANE INSPECTION & MAINTENANCE SERVICES A DIVISION OF AL-KHOBAR GATE INTERNATIONAL TRADING EST.		
	INSPECTION CHECKLIST FOR FORKLIFT		
	FRM.0601-1.15	Revision 00	Issue Date: 01/JAN/2020
	Standards: ANSI/ITSDF B56.1 – 2018, ANSI/ITSDF B56.6 – 2016		

REPORT NO	CIMS6034	INSPECTION DATE	2025-12-26
CLIENT'S NAME	Abdullah Nass & Partners Co. Ltd. (Operation)	INSPECTED BY	Akhil Raj Devarajan
LOCATION	Tanajib Yard	STICKER NO.	31632
EQUIPMENT NO	SD-FL-27	EQUIP. SERIAL NO.	FDA22-1240-01079
EQUIPMENT TYPE	FORKLIFT COUNTERBALANCE	CAPACITY (SWL)	2300 KGS

S.N	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	REMARKS
Section 1. RATINGS & MARKINGS						
1.1	Documentation is available.	ANSI B56.1, Sec.5.1	✓			
1.2	Equipment asset ID Number is prominently marked.	ANSI B56.1, Sec.5.2	✓			
1.3	Nameplate, caution, and instruction markings are available on the truck.	ANSI B56.1, Sec.5.3	✓			
1.4	SWL/WLL (Capacities) are clearly marked & on a prominent location.	ANSI B56.1, Sec.5.4	✓			
1.5	All controls are marked for identification of function.	ANSI B56.1, Sec.5.5	✓			
1.6	Front end attachments, including fork extensions are marked with identification, capacity, maximum elevation with the load laterally centered.	ANSI B56.1, Sec.5.6	✓			
1.7	The machine is operated by Certified Operator.	ANSI B56.1, Sec.5.7	✓			
1.8	All control levers are within reach of operator during the normal operating conditions.	ANSI B56.1, Sec.5.8	✓			
1.9	Capacity chart is provided & legible.	ANSI B56.1, Sec.5.9	✓			
1.10	All safety & warning decals are posted.	ANSI B56.1, Sec.5.10	✓			
Section 2. VISUAL INSPECTION & FUNCTIONAL TEST						
2.1	Carriage, backrest, & mast are not bent or deformed.	ANSI B56.1, Sec.6.1.1	✓			
2.2	Forks are not deformed or bent.	ANSI B56.1, Sec.6.1.2	✓			
2.3	Forks arms & levers are not deformed or bent.	ANSI B56.1, Sec.6.1.3	✓			
2.4	No excessive corrosion on frames, anchorages, structures are present.	ANSI B56.1, Sec.6.1.4	✓			
2.5	Load chains have no broken links or pins.	ANSI B56.1, Sec.6.1.5			✓	
2.6	Lift & tilt cylinders are operating correctly & without hydraulic oil leaks.	ANSI B56.1, Sec.6.1.6	✓			
2.7	Steering & side shift cylinders are operating correctly & without hydraulic oil leaks.	ANSI B56.1, Sec.6.1.7	✓			
2.8	ROPS or overhead guard is provided and can withstand the drop test based on the applicable table or rated capacity.	ANSI B56.1, Sec.6.1.8	✓			
2.9	Safety belt is provided.	ANSI B56.1, Sec.6.1.9	✓			
2.10	All control levers are within reach of operator during the normal operating conditions.	ANSI B56.1, Sec.6.1.10	✓			



CRANE INSPECTION & MAINTENANCE SERVICES

A DIVISION OF AL-KHOBAR GATE INTERNATIONAL TRADING EST

INSPECTION CHECKLIST FOR FORK LIFT

FRM.0601-1.15

Revision 00

Issue Date: 01/JAN/2020

Prepared By
Operations Manager

Reviewed & Approved By
Managing Director



S.N	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	REMARKS
2.11	All hydraulic hoses are free of tears, and no signs of leaks on their hose fittings.	ANSI B56.1, Sec.6.1.11	✓			
2.12	Hydraulic oil tank level is correct and tank is securely fastened, and no signs of oil leakages.	ANSI B56.1, Sec.6.1.12	✓			
2.13	Fuel tank is correct, secured, & not leaking.	ANSI B56.1, Sec.6.1.13	✓			
2.14	Steering & transmission oil levels are correct & not leaking.	ANSI B56.1, Sec.6.1.14	✓			
2.15	Lubrication points are accessible.	ANSI B56.1, Sec.6.1.15	✓			
2.16	No deterioration or leakage in air, water or hydraulic is found.	ANSI B56.1, Sec.6.1.16	✓			
2.17	No indication of loose, damaged, or missing structural components including supports and anchorages.	ANSI B56.1, Sec.6.1.17	✓			
2.18	Limit Switches are properly working.	ANSI B56.1, Sec.6.1.18	✓			
2.19	Brake & Clutch system parts & linings have no excessive wear, severe distortion, and damage.	ANSI B56.1, Sec.6.1.19	✓			
2.20	Seat and back cushion are not torn.	ANSI B56.1, Sec.6.1.20	✓			
Section 3. INSPECTION CRITERIA						
3.1	No deterioration or leakage in air or hydraulic is found.	ANSI B56.1, Sec.7.1.1	✓			
3.2	Tires have no tears, sidewall cuts & excessive wear.	ANSI B56.1, Sec.7.1.2	✓			Backside two tyres have less grip
3.3	Wheel hubs and gear boxes have no leakages.	ANSI B56.1, Sec.7.1.3	✓			
3.4	Wheel bearings / bushing have no signs of excessive wear.	ANSI B56.1, Sec.7.1.4	✓			
3.5	No indication of loose, damaged, or missing components including supports and anchorages on under chassis.	ANSI B56.1, Sec.7.1.5	✓			
3.6	Control & drive mechanisms are properly adjusted and without excessive wear.	ANSI B56.1, Sec.7.1.6	✓			
3.7	Brake fluid level is correctly topped-up.	ANSI B56.1, Sec.7.1.7	✓			
3.8	Parking brake is correctly working.	ANSI B56.1, Sec.7.1.8	✓			
3.9	Steering cylinders, knuckles, kingpins, tie rods, equalizer bar, etc. have no excessive plays and not excessively worn-out.	ANSI B56.1, Sec.7.1.9	✓			
3.10	No damage tubing, piping, electrical cables, or hoses, and their fittings.	ANSI B56.1, Sec.7.1.10	✓			
Section 4. ENGINE & ELECTRICAL SYSTEM						
4.1	Engine has no excessive smoke, & engine oil leak.	ANSI B56.1, Sec.8.1.1	✓			
4.2	Fuel is not leaking.	ANSI B56.1, Sec.8.1.2	✓			
4.3	Engine has no loss of power.	ANSI B56.1, Sec.8.1.3	✓			
4.4	Fan, Alternator, & steering belts tension are not loose.	ANSI B56.1, Sec.8.1.4	✓			
4.5	All indicator lights are not broken and are functioning correctly.	ANSI B56.1, Sec.8.1.5	✓			
4.6	Strobe light or rotating beacon light is provided working.	ANSI B56.1, Sec.8.1.6	✓			
4.7	Head light & working lights are not broken and are functioning correctly.	ANSI B56.1, Sec.8.1.7	✓			
4.8	Brake & tail lights, including reverse light are working.	ANSI B56.1, Sec.8.1.8	✓			
4.9	Back-Up alarm is working.	ANSI B56.1, Sec.8.1.9	✓			
4.10	Horn is working.	ANSI B56.1, Sec.8.1.10	✓			



CRANE INSPECTION & MAINTENANCE SERVICES
A DIVISION OF AL-KHOBAR GATE INTERNATIONAL TRADING EST
INSPECTION CHECKLIST FOR FORK LIFT

FRM.0601-1.15

Revision 00

Issue Date: 01/JAN/2020

Prepared By
Operations Manager

Reviewed & Approved By
Managing Director



S.N	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	REMARKS
4.11	Radiator coolant level is correct and no sign of water leakage.	ANSI B56.1, Sec.8.1.11	✓			
4.12	Turn signal lights are provided and working correctly.	ANSI B56.1, Sec.8.1.12	✓			
4.13	Battery water/electrolyte level is correct.	ANSI B56.1, Sec.8.1.13	✓			
4.14	Fire extinguisher is provided and has the valid inspection tag.	ANSI B56.1, Sec.8.1.14	✓			Extinguisher clip not found during inspection

REMARKS / RECOMMENDATIONS
Satisfactory

INSPECTOR'S NAME:	Akhil Raj Devarajan	CLIENT'S REP. NAME:	AFZAL AHAMAD
SIGNATURE & DATE:	C:/xampp/htdocs/whiteappupdated/inspector/uploads/akhil_raj_devarajan/images/signature_image.jpg	SIGNATURE & DATE:	