Planning Constraints & Triggers Report

Lot/Plan: 3//DP263990

Council: (NSW)

Development type: Dwelling house

Report date: 2026-10-12

Data currency: currency field not returned; fetched 2026-10-12; source currency 2022-03-01; fetched 2026-10-12; source currency 2024-12-13; fetched 2026-10-12; source currency 2026-10-03; fetched 2026-10-12; The NSW BFPL Map is collated and merged together from individual NSW local council maps which are submitted by the local council for certification. The maps are often a product of or derived from local and state vegetation mapping with input from Local Council and RFS staff. In some cases the maps are produced under contract for local council by various companies. Please refer to the individual metadata statements for each LGA BFPL Map. (text from ePlanning/Planning_Portal_Hazard layer 229, same dataset)

This report is informational only. It is NOT a planning certificate (NSW s10.7 certificate) or a council property/planning report. Verify all matters with the council and the relevant authority. Mapping data may be out of date, incomplete or inaccurate. 'Not checked' means the layer could not be queried; it does not mean clear.

Summary of layers

Layer	Status	Overlap m2	% of lot	Footprint	Currency
Flood planning area / flood hazard	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Bushfire prone land (vegetation category and buffer)	Affected	509264.5	100.0	-	source currency 2026-10-03; fetched 2026-1
Heritage item	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Heritage conservation area	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Acid sulfate soils class	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Biodiversity values map	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Coastal management area / coastal wetlands	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Riparian land / water	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Land reservation acquisition	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Airport noise (ANEF) / obstacle limitation	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Mine subsidence district	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Contaminated / potentially contaminated land	Not checked	0.0	0.0	-	no endpoint configured
Transport corridors (road/rail)	Not checked	0.0	0.0	-	no endpoint configured
SEPP-mapped areas	Affected	509264.5	100.0	-	source currency 2022-03-01; fetched 2026-1
Urban release area	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Minimum lot size map	Affected	509264.5	100.0	-	source currency 2024-12-13; fetched 2026-1
Height of buildings map	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-
Floor space ratio map	Not affected	0.0	0.0	-	currency field not returned; fetched 2026-10-

Map: Bushfire prone land (vegetation category and buffer)




Figure 1. Bushfire prone land (vegetation category and buffer): constraint overlay on lot (MGA, indicative)
No aerial imagery available. Vector overlays only.

Overlap 509264.5 m2 (100.0% of lot); nearest distance 0.0 m.

Map: SEPP-mapped areas




Figure 2. SEPP-mapped areas: constraint overlay on lot (MGA, indicative)
No aerial imagery available. Vector overlays only.

Overlap 509264.5 m2 (100.0% of lot); nearest distance 0.0 m.

Triggers and next steps

Bushfire prone land (habitable building) - Bushfire prone land (vegetation category and buffer)

Rule: bushfire.habitable. Source: to be cited from Planning for Bushfire Protection / AS 3959 / NCC.

Attributes: [{'Category': 3, 'd_Category': 'Vegetation Category 3'}]

Pathway (may apply: verify with council): may apply: BAL construction requirements for a habitable building; verify with council / certifier

- bal_assessment_as3959: TO BE CONFIRMED. Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

- pbp_compliance: TO BE CONFIRMED. Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

- spp_bushfire_hazard: TO BE CONFIRMED. Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

- asset_protection_zone: TO BE CONFIRMED. Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

- rfs_referral: TO BE CONFIRMED. Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

Next steps: Commission a BAL assessment (AS 3959) by an accredited practitioner; NSW: check Planning for Bushfire Protection (habitable buildings); Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

Mapped constraint - SEPP-mapped areas

Rule: generic. Source: to be cited.

Attributes: [{'EPI_NAME': 'State Environmental Planning Policy (Resilience and Hazards) 2021', 'LAY_CLASS': 'Land Application'}, {'EPI_NAME': 'State Environmental Planning Policy (Resilience and Hazards) 2021', 'LAY_CLASS': 'Land Application'}]

Pathway (may apply: verify with council): may apply: verify with council

Next steps: Obtain the authoritative statement of what this layer triggers; Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

Mapped constraint - Minimum lot size map

Rule: generic. Source: to be cited.

Attributes: [{'EPI_NAME': 'Gunnedah Local Environmental Plan 2012', 'LAY_CLASS': '200-399.9', 'LOT_SIZE': 200.0, 'UNITS': 'ha'}]

Pathway (may apply: verify with council): may apply: verify with council

Next steps: Obtain the authoritative statement of what this layer triggers; Obtain the s10.7 planning certificate (EP&A Act) for the lot and confirm with the council.

Acknowledgements

- dbyd_physical_verification
- setback_user_verification
- cut_fill_indicative_only
- retaining_wall_not_structural
- crossover_not_certified
- cadastre_not_survey
- uploaded_plan_accuracy
- upload_rights_warranty
- hydrology_not_certified

Legal statement

This report is informational only. It is NOT a planning certificate (NSW s10.7 certificate) or a council property/planning report. Verify all matters with the council and the relevant authority. Mapping data may be out of date, incomplete or inaccurate. 'Not checked' means the layer could not be queried; it does not mean clear.