

## Equipment Maintenance Log

Document No: BPL-MAINT-2024-0147

### Equipment Information

|         |                      |           |                               |
|---------|----------------------|-----------|-------------------------------|
| Tag No. | P-101A               | Equipment | Centrifugal Pump              |
| Model   | KSB Mega CPK 200-330 | Standard  | API 610 Type OH2              |
| Service | Crude Charge Pump    | Location  | Crude Distillation Unit (CDU) |

### Maintenance History (12 Months)

| Date       | Type | Vibration (mm/s) | Bearing Temp (°C) | Findings & Actions                       | Technician |
|------------|------|------------------|-------------------|------------------------------------------|------------|
| 2024-01-15 | PM   | 2.1              | 65                | Routine check. Lubed bearings.           | R. Sharma  |
| 2024-04-12 | PM   | 2.8              | 68                | Vibration slightly high. Monitored.      | A. Patel   |
| 2024-07-20 | CM   | 6.5              | 85                | High vibration alert. Replaced impeller. | K. Singh   |
| 2024-07-22 | Test | 1.5              | 62                | Post-repair run test successful.         | M. Reddy   |
| 2024-10-10 | PM   | 1.8              | 63                | Seal inspection OK. No leaks.            | R. Sharma  |