Westridge Roofing

Professional Roof Measurement Report

608-555-0142
owner@westridge.example

Generated October 28, 2026

4410 Elm Street, Dallas, TX 75201

Source: Google Maps Satellite · **Captured:** 2026-04-02 SPRING HIGH Quality

Spring imagery — early foliage may partially obscure roof edges near trees.



Ridge Valley Hip Rake Eave

20.40	23.50	2,040	4
Total Squares	Squares + 15% Waste	Total Area (sqft)	Roof Segments

AI ROOF ANALYSIS

Condition Score	Material Detected	Tree Overhang
72/100	Shingle	12.0%

Measurement Summary

MEASUREMENT	VALUE
Total Roof Area	2,040 sqft
Total Squares	20.40
Ridge	48 LF
Valley (ice & water shield needed)	19 LF
Hip	22 LF
Rake	56 LF
Eave	104 LF
Total Perimeter	160 LF
Waste Factor	15%
Squares with Waste	23.50
Ice & Water Shield	420 sqft

Segment Details

#	AREA (SQFT)	PITCH	AZIMUTH	FACING
Main south	812	6/12	180°	S
Main north	798	6/12	0°	N
Garage east	310	4/12	90°	E
Porch	120	3/12	270°	W

Disclaimer: This roof measurement report is generated using aerial imagery and automated analysis from the Google Solar API. Measurements are approximate and should be verified by an on-site inspection before being used for material ordering, bidding, or

construction purposes. Actual roof conditions, including hidden damage, structural issues, and complex architectural details, may not be fully captured by aerial imagery. The generating company assumes no liability for inaccuracies in this report.