Gamuda IBS Form detail report

Form detail



#16: Defect Management Form

Forms


Location	SkyMeridian Condominium		
Form date	2025-10-13		
Template	Defect Management Form		
Description	Testing weld quality at Sky Meridian		
Due date	2025-11-30		
Created by	Jeremy Ong		
Status	In Progress		
QA Description	detecting weld quality of sky meridian with multi user (1)		
QA Created by	Jeremy Ong		
Report generated at	2025-10-13-12-00-28		

Detection Summary

Date	Good Weld	Bad Weld	Human Edited	Total Welds
2025-10-13-12-00-28	44.4%	51.9%	3.7%	27
2025-10-13 11:54:06	38.2%	61.8%	0.0%	34
2025-10-13 11:51:46	52.2%	43.5%	4.3%	23
2025-10-13 11:45:55	37.8%	59.5%	2.7%	37
2025-10-13 11:42:28	52.2%	43.5%	4.3%	23



Weld Detection Results Sample - Page 1











0_IMG-20250608-WA...

0_IMG-20250608-WA...










0_IMG-20250608-WA...

1_IMG-20250608-WA...











1_IMG-20250608-WA...